

ME050-3, Picture 1: 5 times 5 visual equidistant *L**-colour steps and Landolt−rings; Use of the PS operator *n000* setcmykcolor*



ME050-5, Picture 2: 32 visual equidistant Δ*Eab**-colour steps, dark steps; Use of the PS operator *n000* setcmykcolor*



ME050-7, Picture 3: 32 visual equidistant Δ*Eab**-colour steps, light steps; Use of the PS operator *n000* setcmykcolor*



ME050-3, Picture 1: 5 times 5 visual equidistant *L**-colour steps and Landolt−rings; Use of the PS operator *0n00* setcmykcolor*



ME050-5, Picture 2: 32 visual equidistant Δ*Eab**-colour steps, dark steps; Use of the PS operator *0n00* setcmykcolor*



ME050-7, Picture 3: 32 visual equidistant Δ*Eab**-colour steps, light steps; Use of the PS operator *0n00* setcmykcolor*



ME050-3, Picture 1: 5 times 5 visual equidistant *L**-colour steps and Landolt−rings; Use of the PS operator *00n0* setcmykcolor*



ME050-5, Picture 2: 32 visual equidistant Δ*Eab**-colour steps, dark steps; Use of the PS operator *00n0* setcmykcolor*



ME050-7, Picture 3: 32 visual equidistant Δ*Eab**-colour steps, light steps; Use of the PS operator *00n0* setcmykcolor*

ME05: Modification of chromatic CEN CSH 99013-test chart no. 3Y
Chart for visual linearization of 5/32 step colour series, Landolt-rings

input: *00n0* setcmykcolor*
output: *00n0* setcmykcolor*



ME050-3, Picture 1: 5 times 5 visual equidistant *L**-colour steps and Landolt−rings; Use of the PS operator *000n* setcmykcolor*



ME050-5, Picture 2: 32 visual equidistant Δ*Eab**-colour steps, dark steps; Use of the PS operator *000n* setcmykcolor*



ME050-7, Picture 3: 32 visual equidistant Δ*Eab**-colour steps, light steps; Use of the PS operator *000n* setcmykcolor*



ME050-3, Picture 1: 5 times 5 visual equidistant *L**-colour steps and Landolt−rings; Use of the PS operator *0nn0* setcmykcolor*



ME050-5, Picture 2: 32 visual equidistant Δ*Eab**-colour steps, dark steps; Use of the PS operator *0nn0* setcmykcolor*



ME050-7, Picture 3: 32 visual equidistant Δ*Eab**-colour steps, light steps; Use of the PS operator *0nn0* setcmykcolor*

ME05: Modification of chromatic CEN CSH 99013-test chart no. 3O
Chart for visual linearization of 5/32 step colour series, Landolt-rings

input: *0nn0* setcmykcolor*
output: *0nn0* setcmykcolor*

-8



ME050-3, Picture 1: 5 times 5 visual equidistant *L**-colour steps and Landolt−rings; Use of the PS operator *n0n0* setcmykcolor*



ME050-5, Picture 2: 32 visual equidistant Δ*Eab**-colour steps, dark steps; Use of the PS operator *n0n0* setcmykcolor*



ME050-7, Picture 3: 32 visual equidistant Δ*Eab**-colour steps, light steps; Use of the PS operator *n0n0* setcmykcolor*



ME050-3, Picture 1: 5 times 5 visual equidistant *L**-colour steps and Landolt−rings; Use of the PS operator *nn00* setcmykcolor*



ME050-5, Picture 2: 32 visual equidistant Δ*Eab**-colour steps, dark steps; Use of the PS operator *nn00* setcmykcolor*



ME050-7, Picture 3: 32 visual equidistant Δ*Eab**-colour steps, light steps; Use of the PS operator *nn00* setcmykcolor*

-8



ME050-3, Picture 1: 5 times 5 visual equidistant *L**-colour steps and Landolt−rings; Use of the PS operator *nnn0* setcmykcolor*



ME050-5, Picture 2: 32 visual equidistant Δ*Eab**-colour steps, dark steps; Use of the PS operator *nnn0* setcmykcolor*



ME050-7, Picture 3: 32 visual equidistant Δ*Eab**-colour steps, light steps; Use of the PS operator *nnn0* setcmykcolor*