See for similar files: http://www.ps.bam.de/TE49/
Technical information: http://www.ps.bam.de Version 2.1, io=1,1, CIEXYZ

BAM registration: 20060101-TE49/10Q/Q49E00F1.PS/.TXT
application for evaluation and measurement of printer or monitor systems, Y=2.5, XYZ
BAM material: code=rha4ta
TE49 for ps.bam.de Job, Sect=1.1, Page 1, Part=1.0, Content=1.1

Input: Colorimetric Reflective System NCS11
for hue $h^* = lab^*h = 24/360 = 0.066$
lab*tch* and *lab*nch

D65: hue R
LCH*Ma: 47 92 24
rgb*Ma: 1.0 0.0 0.0

triangle lightness

%Gamut

$u^*_{rel} = 149$

NCS11; adapted (a) CIELAB data	$L^*=L^*_a$	a^*_a	b^*_a	$C^*_{ab,a}$	$h^*_{ab,a}$
R_{Ma}	47.15	84.64	37.25	92.48	24
J_{Ma}	91.37	−1.27	125.03	125.03	91
G_{Ma}	63.07	−114.28	25.35	117.06	167
$G50B_{Ma}$	59.47	−80.6	−33.45	87.28	203
B_{Ma}	49.01	3.65	−81.19	81.28	273
$B50R_{Ma}$	44.06	106.09	−73.93	129.32	325
N_{Ma}	10.99	0.0	0.0	0.0	0
W_{Ma}	95.41	0.0	0.0	0.0	0
R_{CIE}	39.92	58.69	27.98	65.01	25
J_{CIE}	81.26	−2.9	71.56	71.62	92
G_{CIE}	52.23	−42.45	13.59	44.59	162
B_{CIE}	30.57	1.35	−46.48	46.51	272

%Regularity

$g^*_{H,rel} = 46$

$g^*_{C,rel} = 65$



Output: Colorimetric Reflective System NCS11
for hue $h^* = lab^*h = 24/360 = 0.066$
lab*tch* and *lab*nch

D65: hue R
LCH*Ma: 47 92 24
rgb*Ma: 1.0 0.0 0.0

triangle lightness

%Gamut

$u^*_{rel} = 149$

NCS11; adapted (a) CIELAB data	$L^*=L^*_a$	a^*_a	b^*_a	$C^*_{ab,a}$	$h^*_{ab,a}$
R_{Ma}	47.15	84.64	37.25	92.48	24
J_{Ma}	91.37	−1.27	125.03	125.03	91
G_{Ma}	63.07	−114.28	25.35	117.06	167
$G50B_{Ma}$	59.47	−80.6	−33.45	87.28	203
B_{Ma}	49.01	3.65	−81.19	81.28	273
$B50R_{Ma}$	44.06	106.09	−73.93	129.32	325
N_{Ma}	10.99	0.0	0.0	0.0	0
W_{Ma}	95.41	0.0	0.0	0.0	0
R_{CIE}	39.92	58.69	27.98	65.01	25
J_{CIE}	81.26	−2.9	71.56	71.62	92
G_{CIE}	52.23	−42.45	13.59	44.59	162
B_{CIE}	30.57	1.35	−46.48	46.51	272

%Regularity

$g^*_{H,rel} = 46$

$g^*_{C,rel} = 65$

TE490–7, 5 step scales for constant CIELAB hue 24/360 = 0.066 (left)

5 step scales for constant CIELAB hue 24/360 = 0.066 (right)

BAM-test chart TE49; Colorimetric systems NCS11a & NCS11a input: *olv* setrgbcolor*
D65: 5 step colour scales and coordinate data for 10 hues output: *olv* setrgbcolor / w* setgray*