

Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *www* setrgbcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *www* setrgbcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *www* setrgbcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *www* setrgbcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *www* setrgbcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *www* setrgbcolor*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *www* setrgbcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *www* setrgbcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *www* setrgbcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *www* setrgbcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *www* setrgbcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *www* setrgbcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *www* setrgbcolor*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *www* setrgbcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *www* setrgbcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *www* setrgbcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *www* setrgbcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *www* setrgbcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *www* setrgbcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *www* setrgbcolor*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *www* setrgbcolor*
output: *no change compared to input*

www.ps.bam.de/CE67/10Q/Q67E30SP.PS/.PDF;
S: Output Linearization (OL) data CE67/10Q/Q67E30SP.DAT in Distiller Startup (S) Directory



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *www* setrgbcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *www* setrgbcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *www* setrgbcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *www* setrgbcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *www* setrgbcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *www* setrgbcolor*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *www* setrgbcolor*
output: *no change compared to input*

See for similar files: http://www.ps.bam.de/CE67/
Technical information: http://www.ps.bam.de/9241

Version 2.0, io=3,3, CIELAB, 1.0 exp

BAM registration: 20040101-CE67/10Q/Q67E30SP.PS/.PDF
Application for achromatic display output with CIELAB contrast range *L*w:L*n* = 95.4 : 0.0

BAM material: code=rha4ta



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *www* setrgbcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *www* setrgbcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *www* setrgbcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *www* setrgbcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *www* setrgbcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *www* setrgbcolor*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *www* setrgbcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *www* setrgbcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *www* setrgbcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *www* setrgbcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *www* setrgbcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *www* setrgbcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *www* setrgbcolor*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *www* setrgbcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *www* setrgbcolor*



Picture C2: 5 visual equidistant L^*-grey steps + *N0* + *W1*; PS operator: *www* setrgbcolor*



Picture C3: 16 visual equidistant L^*-grey steps; PS operator: *www* setrgbcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *www* setrgbcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *www* setrgbcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *www* setrgbcolor*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *www* setrgbcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *www* setrgbcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *www* setrgbcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *www* setrgbcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *www* setrgbcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *www* setrgbcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *www* setrgbcolor*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *www* setrgbcolor*
output: *no change compared to input*