

Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *nnn0* setcmykcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *cmy0* setcmykcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *nnn0* setcmykcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *nnn0* setcmykcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *nnn0* setcmykcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *nnn0* setcmykcolor*

ISO 9241−test chart for contrast range *Yw:Yn* = 88.6 : 2.5
Ergonomics − Visual Displays − Field Assessment Methods

input: *nnn0* setcmykcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *nnn0* setcmykcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *cmy0* setcmykcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *nnn0* setcmykcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *nnn0* setcmykcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *nnn0* setcmykcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *nnn0* setcmykcolor*

ISO 9241−test chart for contrast range *Yw:Yn* = 88.6 : 2.5
Ergonomics − Visual Displays − Field Assessment Methods

input: *nnn0* setcmykcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *nnn0* setcmykcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *cmy0* setcmykcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *nnn0* setcmykcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *nnn0* setcmykcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *nnn0* setcmykcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *nnn0* setcmykcolor*

ISO 9241−test chart for contrast range *Yw:Yn* = 88.6 : 2.5
Ergonomics − Visual Displays − Field Assessment Methods

input: *nnn0* setcmykcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *nnn0* setcmykcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *cmy0* setcmykcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *nnn0* setcmykcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *nnn0* setcmykcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *nnn0* setcmykcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *nnn0* setcmykcolor*

ISO 9241−test chart for contrast range *Yw:Yn* = 88.6 : 2.5
Ergonomics − Visual Displays − Field Assessment Methods

input: *nnn0* setcmykcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *nnn0* setcmykcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *cmy0* setcmykcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *nnn0* setcmykcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *nnn0* setcmykcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *nnn0* setcmykcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *nnn0* setcmykcolor*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *nnn0* setcmykcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *cmy0* setcmykcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *nnn0* setcmykcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *nnn0* setcmykcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *nnn0* setcmykcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *nnn0* setcmykcolor*

ISO 9241−test chart for contrast range *Yw:Yn* = 88.6 : 2.5
Ergonomics − Visual Displays − Field Assessment Methods

input: *nnn0* setcmykcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *nnn0* setcmykcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *cmy0* setcmykcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *nnn0* setcmykcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *nnn0* setcmykcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *nnn0* setcmykcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *nnn0* setcmykcolor*

ISO 9241−test chart for contrast range *Yw:Yn* = 88.6 : 2.5
Ergonomics − Visual Displays − Field Assessment Methods

input: *nnn0* setcmykcolor*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *nnn0* setcmykcolor*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *cmy0* setcmykcolor*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *nnn0* setcmykcolor*



Picture C4: Landolt-rings *W-N*; PS operator: *nnn0* setcmykcolor*



Picture C5: Line raster under 45° (or 135°); PS operator: *nnn0* setcmykcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *nnn0* setcmykcolor*

ISO 9241−test chart for contrast range *Yw:Yn* = 88.6 : 2.5
Ergonomics − Visual Displays − Field Assessment Methods

input: *nnn0* setcmykcolor*
output: *no change compared to input*