www.ps.bam.de/DE50/10T/T50E00CP.PS/.PDF; start output with LAB* transfer and no OL
N: No Output Linearization (OL) data in File (F), Startup (S) or Device (D)

Information and Order: http://www.ps.bam.de Image file version 1.5, 20011015-DE50

BAM registration: 20011015-DE50/10T/T50E00CP.PS/.PDF BAM material: code=rha4ra



Figure B4 and/or D4 of the ISO/IEC-test charts; *w* - cmyn*; w* - olv(cmy)*;* 16 visual equidistant steps of colour series*: LAB* -> ΔLAB*;* LM methods: N, F, S, D, T, E

16 colours according to ISO/IEC 15775 and 19839-X; setcolor -> setcmykcolor, setgray