




Picture 5: 16 equidistant steps for "measurement", "banding" and "strike through"; Use of PS operator; B4: $\text{cmy0}^* / 000n^* \text{ setcmycolor}$; D4: $\text{cmy0}^* \text{ setcmycolor}$ (only)