





Picture B1: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (sf); PS operators *settransfer*, 4 *colorimage*




Picture D2: Radial gratings *W-O*, *W-L*, *W-V*, *W-N*, and *W-Z*; Use of PS operator *LAB* setcolor*




Picture B3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *LAB* setcolor*


Fig. B1 to B7 of ISO/IEC-test chart 2;




Picture B4: 16 equidistant steps *W-C*, *W-M*, *W-Y* and *W-N*; PS operator *LAB* setcolor*



Picture D5: Script and Landolt-rings *N*, *C*, *M* and *Y*; Use of PS operator *LAB* setcolor*



Picture B6: Landolt-rings *W-C* and *W-M*; Use of PS operator *LAB* setcolor*



Picture B7: Landolt-rings *W-Y* and *W-N*; Use of PS operator *LAB* setcolor*