






16 step scales for constant CIELAB hue $92/360 = 0.254$ (right)




XE690-7, 9 step scales for constant CIELAB hue 143/360 = 0.398 (left)

16 step scales for constant CIELAB hue 143/360 = 0.398 (right)




XE690-7, 9 step scales for constant CIELAB hue 232/360 = 0.644 (left)

16 step scales for constant CIELAB hue 232/360 = 0.644 (right)




XE690-7, 9 step scales for constant CIELAB hue 312/360 = 0.867 (left)


16 step scales for constant CIELAB hue 312/360 = 0.867 (right)



XE690-7, 9 step scales for constant CIELAB hue 337/360 = 0.937 (left)


16 step scales for constant CIELAB hue 337/360 = 0.937 (right)






XE690-7, 9 step scales for constant CIELAB hue 92/360 = 0.255 (left)

16 step scales for constant CIELAB hue 92/360 = 0.255 (right)



XE690-7, 9 step scales for constant CIELAB hue 158/360 = 0.438 (left)

16 step scales for constant CIELAB hue 158/360 = 0.438 (right)



XE690-7, 9 step scales for constant CIELAB hue 273/360 = 0.76 (left)

16 step scales for constant CIELAB hue 273/360 = 0.76 (right)