





AE90-1, D50 Illuminant, 2 degree observer, $x_0 = 0.64516$, $y_0 = 0.35484$, $z_0 = 0.00000$, $\gamma_p = 0.924$




AE90-1, D50 Illuminant, 2 degree observer, $x_0 = 0.64516$, $y_0 = 0.35484$, $z_0 = 0.00000$, $\gamma_p = 0.924$




AE90-1, D50 Illuminant, 2 degree observer, $x_0 = 0.64516$, $y_0 = 0.35484$, $z_0 = 0.00000$, $\gamma_p = 0.924$



AE90-1, D50 Illuminant, 2 degree observer, $x_0 = 0.64516$, $y_0 = 0.35484$, $z_0 = 0.00000$, $\gamma_p = 0.924$



AE90-1, D50 Illuminant, 2 degree observer, $x_0 = 0.64516$, $y_0 = 0.35484$, $z_0 = 0.00000$, $\gamma_p = 0.924$



AE90-1, D50 Illuminant, 2 degree observer, $x_0 = 0.64516$, $y_0 = 0.35484$, $z_0 = 0.00000$, $\gamma_p = 0.924$