

HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{l}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{D65: } \Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 101,19$$

$$x_{\text{F02_X,s}} = 0,3133$$

$$y_{\text{F02_X,s}} = 0,3306$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{D50: } \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 102,64$$

$$x_{\text{F02_X,s}} = 0,3484$$

$$y_{\text{F02_X,s}} = 0,3607$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$P40: \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 104,36$$

$$x_{\text{F02_X,s}} = 0,3831$$

$$y_{\text{F02_X,s}} = 0,3775$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$A00: \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 107,48$$

$$x_{\text{F02_X,s}} = 0,4527$$

$$y_{\text{F02_X,s}} = 0,4087$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$E00: \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 102,59$$

$$x_{\text{F02_X,s}} = 0,3331$$

$$y_{\text{F02_X,s}} = 0,3330$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$C00: \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 101,38$$

$$x_{\text{F02_X,s}} = 0,3101$$

$$y_{\text{F02_X,s}} = 0,3185$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$P00: \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 103,86$$

$$x_{\text{F02_X,s}} = 0,3617$$

$$y_{\text{F02_X,s}} = 0,3534$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$

$$\bar{l}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$Q00: \Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 101,34$$

$$x_{\text{F02_X,s}} = 0,3054$$

$$y_{\text{F02_X,s}} = 0,3099$$

