

HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X},s}(\lambda) = B_{31}\bar{x}_{\text{F02_X},s}(\lambda) + B_{32}\bar{y}_{\text{F02_X},s}(\lambda) + B_{33}\bar{z}_{\text{F02_X},s}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$\text{D65: } \Sigma \bar{s}_{\text{F02_X},s}(\lambda) = 55,64$$

$$x_{\text{F02_X},s} = 0,3133$$

$$y_{\text{F02_X},s} = 0,3306$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X},s}(\lambda) = B_{31}\bar{x}_{\text{F02_X},s}(\lambda) + B_{32}\bar{y}_{\text{F02_X},s}(\lambda) + B_{33}\bar{z}_{\text{F02_X},s}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$\text{D50: } \Sigma \bar{s}_{\text{F02_X},s}(\lambda) = 41,65$$

$$x_{\text{F02_X},s} = 0,3484$$

$$y_{\text{F02_X},s} = 0,3607$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X},s}(\lambda) = B_{31}\bar{x}_{\text{F02_X},s}(\lambda) + B_{32}\bar{y}_{\text{F02_X},s}(\lambda) + B_{33}\bar{z}_{\text{F02_X},s}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$P40: \Sigma \bar{s}_{\text{F02_X},s}(\lambda) = 32,75$$

$$x_{\text{F02_X},s} = 0,3831$$

$$y_{\text{F02_X},s} = 0,3775$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X},s}(\lambda) = B_{31}\bar{x}_{\text{F02_X},s}(\lambda) + B_{32}\bar{y}_{\text{F02_X},s}(\lambda) + B_{33}\bar{z}_{\text{F02_X},s}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$A00: \Sigma \bar{s}_{\text{F02_X},s}(\lambda) = 17,51$$

$$x_{\text{F02_X},s} = 0,4527$$

$$y_{\text{F02_X},s} = 0,4087$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X},s}(\lambda) = B_{31}\bar{x}_{\text{F02_X},s}(\lambda) + B_{32}\bar{y}_{\text{F02_X},s}(\lambda) + B_{33}\bar{z}_{\text{F02_X},s}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$E00: \Sigma \bar{s}_{\text{F02_X},s}(\lambda) = 51,78$$

$$x_{\text{F02_X},s} = 0,3331$$

$$y_{\text{F02_X},s} = 0,3330$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X},s}(\lambda) = B_{31}\bar{x}_{\text{F02_X},s}(\lambda) + B_{32}\bar{y}_{\text{F02_X},s}(\lambda) + B_{33}\bar{z}_{\text{F02_X},s}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$C00: \Sigma \bar{s}_{\text{F02_X},s}(\lambda) = 60,22$$

$$x_{\text{F02_X},s} = 0,3101$$

$$y_{\text{F02_X},s} = 0,3185$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X},s}(\lambda) = B_{31}\bar{x}_{\text{F02_X},s}(\lambda) + B_{32}\bar{y}_{\text{F02_X},s}(\lambda) + B_{33}\bar{z}_{\text{F02_X},s}(\lambda)$$

B_{3j} 0,000 0,000 0,5168 $\lambda=440$

P00: $\Sigma \bar{s}_{\text{F02_X},s}(\lambda) = 41,65$

$x_{\text{F02_X},s} = 0,3617$

$y_{\text{F02_X},s} = 0,3534$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$

$$\bar{s}_{\text{F02_X},s}(\lambda) = B_{31}\bar{x}_{\text{F02_X},s}(\lambda) + B_{32}\bar{y}_{\text{F02_X},s}(\lambda) + B_{33}\bar{z}_{\text{F02_X},s}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$Q00: \Sigma \bar{s}_{\text{F02_X},s}(\lambda) = 64,12$$

$$x_{\text{F02_X},s} = 0,3054$$

$$y_{\text{F02_X},s} = 0,3099$$

