



Colorimetric transformation $i = 0$

$$c_i^* = c_0^* = a c^{*b} \text{ with } a = 1,00; b = 1,00$$



Colorimetric transformation $i = 1$

$$c_i^* = c_1^* = a c^{*b} \text{ with } a = 1,00; b = 0,75$$





Colorimetric transformation $i = 2$

$$c_i^* = c_2^* = a c^{*b} \text{ with } a = 1,00; b = 0,50$$




Colorimetric transformation $i = 3$

$$c_i^* = c_3^* = a c^{*b} \text{ with } a = 1,00; b = 2,00$$




Colorimetric transformation $i = 4$

$$c_i^* = c_4^* = a c^{*b} \text{ with } a = 0,75; b = 1,00$$



Colorimetric transformation $i = 5$

$$c_i^* = c_5^* = a c^{*b} \text{ with } a = 0,50; b = 1,00$$



Colorimetric transformation $i = 6$

$$c_i^* = c_6^* = a c^{*b} \text{ with } a = 0,25; b = 1,00$$



Colorimetric transformation $i = 7$

$$c_i^* = c_7^* = a c^{*b} \text{ with } a = 0,00; b = 1,00$$

