


<http://130.149.60.45/~farbmetrik/OE67/OE67L0NA.TXT> /.PS; start output, Page 1/3
N: No Output Linearization (OL) data in File (F), Startup (S) or Device (D)



OE670-7, Picture B1-030-0: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (nf); PS operators *settransfer*, 3 *colorimage*




Radial grating W-C_e Radial grating W-M_e Radial grating W-J_e Radial grating W-N Radial grating W-Z

OE670-5, Picture B2W-030-0: Radial gratings W-C_e; W-M_e; W-J_e; W-N; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$




OE670-7, Picture B3W-030-0: 14 CIE-test colours and 2 + 16 grey steps; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$


OE67: Test chart 2 according to ISO 15775, TR 24705; DH
Image, radial gratings, 16 step colour scales, Landolt-rings




OE671-1, Picture B4W-L-030-0: 16 equidistant steps W-C_e; W-M_e; W-J_e; W-N; PS: $\rightarrow \text{rgb}_e \text{ setrgbcolor}$



OE671-3, Picture B5W-030-0: Script and Landolt-rings N; C_e; M_e; Y_e; Z; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$



OE671-5, Picture B6W-L-030-0: Landolt-rings W-C_e; W-M_e; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$



OE671-7, Picture B7W-L-030-0: Landolt-rings W-J_e; W-N; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$

input: *rgb* ($\rightarrow \text{rgb}_e$) *setrgbcolor*
output 030-0: no change