




http://130.149.60.45/~farbmetrik/RE97/RE97L0NP.PDF /.PS; transfer output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2







RE970-3, Picture D1We: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (sf); ; PS operator 4 colorimage



radial gratings W-Re radial gratings W-Ge radial gratings W-Be radial gratings W-N radial gratings W-Z

RE970-5, Picture D2We: radial gratings W-Re; W-Ge; W-Be; W-N; PS operator rgb->rgb_e setrgbcolorRE970-7, Picture D3We: 14 CIE-test colours and 2 + 16 grey steps (sf); rgb/cmy0->rgb_e setrgbcolor

test chart RE97; 4(ISO/IEC 15775 + ISO/IEC TR 24705)
chromatic test chart RGB, 3D=0, de=1, cmyk

RE971-1, Picture D4We: 16 equidistant steps W-Re; W-Ge; W-Be; W-N; rgb/cmy0->rgb_e setrgbcolorRE971-3, Picture D5We: Sript and Landolt-rings N; Re; Ge; Be; Z; PS operator rgb->rgb_e setrgbcolorRE971-5, Picture D6We: Landolt-rings W-Re; W-Ge; PS operator rgb->rgb_e setrgbcolorRE971-7, Picture D7We: Landolt-rings W-Be; W-N; PS operator rgb->rgb_e setrgbcolor

input: rgb/cmyk -> rgb_e
output: transfer to cmyk_e