





http://130.149.60.45/~farbmeterik/RE98/RE98L0NP.PDF /.PS; transfer output


N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2

see similar files: http://130.149.60.45/~farbmeterik/RE98/RE98L0NP.PDF /.PS; transfer output
technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmeterik


RE980-3, Picture A1We: Element A: radial gratings N-W, W-N, N-Z and W-Z; PS operator: w* setgray

RE980-5, Picture A2We: Element B: 5 visual equidistant L^* -gray steps + N_0 + W_1 ; PS operator: w* setgrayRE980-7, Picture A3We: Element C: 16 visual equidistant L^* -gray steps; PS operator: w* setgraytest chart RE98; ME16(ISO 9241-306), 3(ISO/IEC 15775)
achromatic test chart N, 3D=0, de=1, cmykinput: $rgb/cmyk \rightarrow rgb_e$
output: transfer to $cmyk_e$ 

RE981-1, Picture A4We: Element D: Landolt-rings W-N; PS operator: w* setgray



RE981-3, Picture A5We: Element E: Line raster under 45° (or 135°); PS operator: w* setgray



RE981-5, Picture A6We: Element F: Line raster under 90° (or 0°); PS operator: w* setgray

