



http://130.149.60.45/~farbmetrik/RE99/RE99L0NP.PDF /.PS; transfer output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2


see similar files: http://130.149.60.45/~farbmetrik/RE99/RE99L0NP.PDF /.PS; transfer output
technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik



RE990-3, Picture A1We: Element A: radial gratings N-W, W-N, N-Z and W-Z; PS operator: w* setgray




RE990-5, Picture A2We: Element B: 5 visual equidistant L*-gray steps + N0 + W1; PS operator: w* setgray




RE990-7, Picture A3We: Element C: 16 visual equidistant L*-gray steps; PS operator: w* setgray

test chart RE99; ME16(ISO 9241-306), 3(ISO/IEC 15775)
achromatic test chart N, 3D=0, de=1, sRGB


input: rgb/cmyk -> rgb_e
output: transfer to rgb_e



RE991-1, Picture A4We: Element D: Landolt-rings W-N; PS operator: w* setgray



RE991-3, Picture A5We: Element E: Line raster under 45° (or 135°); PS operator: w* setgray



RE991-5, Picture A6We: Element F: Line raster under 90° (or 0°); PS operator: w* setgray

