


<http://130.149.60.45/~farbmetrik/PE40/PE40L0NP.PDF> / .PS; transfer output

N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2

see similar files: <http://130.149.60.45/~farbmetrik/PE40/PE40.HTM>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmetrik>

TUB registration: 20130201-PE40/PE40L0NP.PDF / .PS
application for measurement of display output, no separation

TUB material: code=rha4ta



TUB-test chart PE40; standard test chart
1080 standard colours, 3D=0, de=0, sRGB

input: $rgb/cmyk \rightarrow rgb_d$
output: transfer to rgb_d