


<http://130.149.60.45/~farbmatrik/PE40/PE40L0NP.PDF> /PS; transfer output

N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2

see similar files: <http://130.149.60.45/~farbmatrik/PE40/PE40.HTM>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmatrik>

TUB registration: 20130201-PE40/PE40L0NP.PDF /PS
application for measurement of display output, no separation

TUB material: code=rha4ta



TUB-test chart PE40; standard test chart
1080 standard colours, 3D=0, de=1, sRGB

input: *rgb/cmyk* -> *rgb_e*
output: transfer to *rgb_e*