


http://130.149.60.45/~farbmetrik/TE86/TE86L0NP.PDF /.PS; transfer output






N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2



TE860-3, Picture D1We: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (sf); PS operator: 4 colorimage



radial gratings W-Re radial gratings W-Ge radial gratings W-Be radial gratings W-N radial gratings W-Z

TE860-5, Picture D2We: radial gratings W-Re; W-Ge; W-Be; W-N; PS operator: rgb->rgb_e setrgbcolorTE860-7, Picture D3We: 14 CIE-test colours and 2 + 16 grey steps (sf); PS operator: rgb/cmy0->rgb_e setrgbcolortest chart TE86; 4(ISO/IEC 15775 + ISO/IEC TR 24705)
chromatic test chart RGB, 3D=0, de=1, cmy0TE861-1, Picture D4We: 16 equidistant steps W-Re; W-Ge; W-Be; W-N; rgb/cmy0->rgb_e setrgbcolorTE861-3, Picture D5We: Sript and Landolt-rings N; Re; Ge; Be; Z; PS operator: rgb->rgb_e setrgbcolorTE861-5, Picture D6We: Landolt-rings W-Re; W-Ge; PS operator: rgb->rgb_e setrgbcolorTE861-7, Picture D7We: Landolt-rings W-Be; W-N; PS operator: rgb->rgb_e setrgbcolorinput: rgb/cmyk -> rgb_e
output: transfer to cmy0_e