


http://130.149.60.45/~farbmatrik/TE96/TE96L0N1.TXT /PS; start output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 1/1




TE960-3, Picture B1W--: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (af); ; PS operators 4 colorimage




radial gratings W-C. radial gratings W-M. radial gratings W-Y. radial gratings W-N radial gratings W-Z

TE960-5, Picture B2W--: radial gratings W-C.; W-M.; W-Y.; W-N; PS operator: rgb setrgbcolor




TE960-7, Picture B3W--: 14 CIE-test colours and 2 + 16 grey steps (sf); PS operator:rgb/cmy0 set(rgb/cmyk)color


test chart TE96; 2(ISO/IEC 15775 + ISO/IEC TR 24705)
chromatic test chart CMY




TE961-1, Picture B4W--: 16 equidistant steps W-C.; W-M.; W-Y.; W-N; rgb/cmy0 set(rgb/cmyk)color



TE961-3, Picture B5W--: Sript and Landolt-rings N; C.; M.; Y.; Z; PS operator: rgb->rgb. setrgbcolor



TE961-5, Picture B6W--: Landolt-rings W-C.; W-M.; PS operator:rgb setrgbcolor



TE961-7, Picture B7W--: Landolt-rings W-Y.; W-N; PS operator:rgb setrgbcolor

input: rgb/cmyk -> w/rgb/cmyk-
output: no change