

$XYZ_w=95.0443, 100.0, 108.89$

$a^* = 500 (a' - a'_{n0}) Y^{1/3}$

$b^* = 500 (b' - b'_{n0}) Y^{1/3}$


$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = D65$



$XYZ_w=96.4228, 100.0, 82.49$

$$a^* = 500 (a' - a'_{n*}) Y^{1/3}$$

$$b^* = 500 (b' - b'_{n*}) Y^{1/3}$$

$$a = a_2 [x/y + 1]$$

$$b = b_2 [z/y + 1/6]^{1/3}$$

$$a_2 = 1/15 = 0.06666$$

$$b_2 = -1/12 = -0.08333$$

$$n = D50$$

LABHNU1 79

Name und Farbart

$$R_{d,sRGB} \quad x=0,64 \quad y=0,33$$

$$G_{d,sRGB} \quad x=0,30 \quad y=0,60$$

$$B_{d,sRGB} \quad x=0,18 \quad y=0,06$$

Geräte- & Elementarfärbungen, $Y_w=100$


des sRGB-Farbraums für D50

in Buntheitsdiagramm (A^* , B^*)

B^*

B^*

Parameter: c_{ab}



$XYZ_w=100.932, 100.0, 64.68$

$a^* = 500 (a' - a'_{n0}) Y^{1/3}$

$b^* = 500 (b' - b'_{n0}) Y^{1/3}$

$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = P40$

LABHNU1 79

Name und Farbart

$R_{d,sRGB} \quad x=0,64 \quad y=0,33$

$G_{d,sRGB} \quad x=0,30 \quad y=0,60$

$B_{d,sRGB} \quad x=0,18 \quad y=0,06$

Geräte- & Elementarfärbungen, $Y_w=100$

des sRGB-Farbraums für P40


in Buntheitsdiagramm (A^*, B^*)

B^*

\uparrow

120

Parameter: c_{ab}



$XYZ_w=109.849, 100.0, 35.58$

$$a^* = 500 (a' - a'_{n*}) Y^{1/3}$$

$$b^* = 500 (b' - b'_{n*}) Y^{1/3}$$

$$a = a_2 [x/y + 1]$$

$$b = b_2 [z/y + 1/6]^{1/3}$$

$$a_2 = 1/15 = 0.06666$$

$$b_2 = -1/12 = -0.08333$$

$$n = A00$$

LABHNU1 79

Name und Farbart

$$R_{d,sRGB} \quad x=0,64 \quad y=0,33$$

$$G_{d,sRGB} \quad x=0,30 \quad y=0,60$$

$$B_{d,sRGB} \quad x=0,18 \quad y=0,06$$

Geräte- & Elementarfärbungen, $Y_W=100$


des sRGB-Farbenraums für A00

in Buntheitsdiagramm (A^*, B^*)

B^*

A^*

Parameter: c_{ab}



$XYZ_w=100.001, 100.0, 100.0$

$a^* = 500 (a' - a'_{n}) Y^{1/3}$

$b^* = 500 (b' - b'_{n}) Y^{1/3}$

$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = E00$

LABHNU1 79

Name und Farbart

$R_{d,sRGB} \quad x=0,64 \quad y=0,33$

$G_{d,sRGB} \quad x=0,30 \quad y=0,60$

$B_{d,sRGB} \quad x=0,18 \quad y=0,06$

Geräte- & Elementarfärbungen, $Y_w=100$


des sRGB-Farbraums für E00

in Buntheitsdiagramm (A^* , B^*)

B^*

B^*

Parameter: c_{ab}



$XYZ_w=98.0718, 100.0, 118.22$

$$a^* = 500 (a' - a'_{n*}) Y^{1/3}$$

$$b^* = 500 (b' - b'_{n*}) Y^{1/3}$$

$$a = a_2 [x/y + 1]$$

$$b = b_2 [z/y + 1/6]^{1/3}$$

$$a_2 = 1/15 = 0.06666$$

$$b_2 = -1/12 = -0.08333$$

$$n = C00$$

LABHNU1 79

Name und Farbart

$$R_{d,sRGB} \quad x=0,64 \quad y=0,33$$

$$G_{d,sRGB} \quad x=0,30 \quad y=0,60$$

$$B_{d,sRGB} \quad x=0,18 \quad y=0,06$$

Geräte- & Elementarfärbungen, $Y_W=100$

des sRGB-Farbenraums für C00


in Buntheitsdiagramm (A^* , B^*)

B^*

B^*

120

Parameter: c_{ab}



$XYZ_w=102.067, 100.0, 81.06$

$$a^* = 500 (a' - a'_{n*}) Y^{1/3}$$

$$b^* = 500 (b' - b'_{n*}) Y^{1/3}$$

$$a = a_2 [x/y + 1]$$

$$b = b_2 [z/y + 1/6]^{1/3}$$

$$a_2 = 1/15 = 0.06666$$

$$b_2 = -1/12 = -0.08333$$

$$n = P00$$

LABHNU1 79

Name und Farbart

$$R_{d,sRGB} \quad x=0,64 \quad y=0,33$$

$$G_{d,sRGB} \quad x=0,30 \quad y=0,60$$

$$B_{d,sRGB} \quad x=0,18 \quad y=0,06$$

Geräte- & Elementarfärbungen, $Y_w=100$


des sRGB-Farbenraums für P00

in Buntheitsdiagramm (A^* , B^*)

B^*

120

Parameter: c_{ab}



$XYZ_w=97.9332, 100.0, 118.95$

$a^* = 500 (a' - a'_{n0}) Y^{1/3}$

$b^* = 500 (b' - b'_{n0}) Y^{1/3}$


$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = Q00$



LABHNU1 79

Name und Farbart

$R_{d,sRGB} \quad x=0,64 \quad y=0,33$

$G_{d,sRGB} \quad x=0,30 \quad y=0,60$

$B_{d,sRGB} \quad x=0,18 \quad y=0,06$

Geräte- & Elementarfärbungen, $Y_W=100$

des $sRGB$ -Farbenraums für Q00

in Buntheitsdiagramm (A^* , B^*)

$XYZ_w=94.8136, 100.0, 107.33$

$a^* = 500 (a' - a'_{n0}) Y^{1/3}$

$b^* = 500 (b' - b'_{n0}) Y^{1/3}$

$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = D65$

LABHNU1 79

Name und Farbart

$R_{d,sRGB} \quad x=0,64 \quad y=0,33$

$G_{d,sRGB} \quad x=0,30 \quad y=0,60$

$B_{d,sRGB} \quad x=0,18 \quad y=0,06$

Geräte- & Elementarfärbungen, $Y_w=100$


des sRGB-Farbraums für D65

in Buntheitsdiagramm (A^* , B^*)

B^*

120

Parameter: c_{ab}



$XYZ_w=96.7256, 100.0, 81.41$

$$a^* = 500 (a' - a'_{n*}) Y^{1/3}$$

$$b^* = 500 (b' - b'_{n*}) Y^{1/3}$$

$$a = a_2 [x/y + 1]$$

$$b = b_2 [z/y + 1/6]^{1/3}$$

$$a_2 = 1/15 = 0.06666$$

$$b_2 = -1/12 = -0.08333$$

$$n = D50$$

LABHNU1 79

Name und Farbart

$$R_{d,sRGB} \quad x=0,64 \quad y=0,33$$

$$G_{d,sRGB} \quad x=0,30 \quad y=0,60$$

$$B_{d,sRGB} \quad x=0,18 \quad y=0,06$$

Geräte- & Elementarfärbungen, $Y_w=100$


des sRGB-Farbraums für D50

in Buntheitsdiagramm (A^* , B^*)

B^*

120

Parameter: c_{ab}



$XYZ_w=101.751, 100.0, 64.44$

$a^* = 500 (a' - a'_{n*}) Y^{1/3}$

$b^* = 500 (b' - b'_{n*}) Y^{1/3}$

$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = P40$

LABHNU1 79

Name und Farbart

$R_{d,sRGB} \quad x=0,64 \quad y=0,33$

$G_{d,sRGB} \quad x=0,30 \quad y=0,60$

$B_{d,sRGB} \quad x=0,18 \quad y=0,06$

Geräte- & Elementarfärbungen, $Y_w=100$

des sRGB-Farbenraums für P40

in Buntheitsdiagramm (A^*, B^*)

B^*

\uparrow

120

120

\downarrow

P40

\downarrow

\leftarrow

-120

-120

\leftarrow

0.55

\leftarrow

0.21

\leftarrow

0.94

\leftarrow

0.94

\leftarrow

1.04

\leftarrow

1.03

\leftarrow

5/22

\leftarrow

1.04

\leftarrow

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

0.41

\leftarrow

$XYZ_w=111.15, 100.0, 35.19$

$$a^* = 500 (a' - a'_{n0}) Y^{1/3}$$

$$b^* = 500 (b' - b'_{n0}) Y^{1/3}$$

$$a = a_2 [x/y + 1]$$

$$b = b_2 [z/y + 1/6]^{1/3}$$

$$a_2 = 1/15 = 0.06666$$

$$b_2 = -1/12 = -0.08333$$

$$n = A00$$

LABHNU1 79

Name und Farbart

$$R_{d,sRGB} \quad x=0,64 \quad y=0,33$$

$$G_{d,sRGB} \quad x=0,30 \quad y=0,60$$

$$B_{d,sRGB} \quad x=0,18 \quad y=0,06$$

Geräte- & Elementarfärbungen, $Y_W=100$

des sRGB-Farbenraums für A00


in Buntheitsdiagramm (A^*, B^*)

B^*

\uparrow

120

-120



$XYZ_w=99.9908, 99.9999, 100.0$

$a^* = 500 (a' - a'_{n}) Y^{1/3}$

$b^* = 500 (b' - b'_{n}) Y^{1/3}$

$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = E00$

LABHNU1 79

Name und Farbart

$R_{d,sRGB} \quad x=0,64 \quad y=0,33$

$G_{d,sRGB} \quad x=0,30 \quad y=0,60$

$B_{d,sRGB} \quad x=0,18 \quad y=0,06$

Geräte- & Elementarfärbungen, $Y_w=100$

des sRGB-Farbraums für E00

in Buntheitsdiagramm (A^* , B^*)

B^*

\uparrow

120


E00

-120

Parame-
ter: c_{ab}

\rightarrow

A^*



$XYZ_w=97.2866, 100.0, 116.14$

$a^* = 500 (a' - a'_{n*}) Y^{1/3}$

$b^* = 500 (b' - b'_{n*}) Y^{1/3}$

$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = C00$

LABHNU1 79

Name und Farbart

$R_{d,sRGB} \quad x=0,64 \quad y=0,33$

$G_{d,sRGB} \quad x=0,30 \quad y=0,60$

$B_{d,sRGB} \quad x=0,18 \quad y=0,06$

Geräte- & Elementarfärbungen, $Y_W=100$


des sRGB-Farbraums für C00

in Buntheitsdiagramm (A^* , B^*)

B^*

120

Parameter: c_{ab}



$XYZ_w=102.375, 100.0, 81.25$

$$a^* = 500 (a' - a'_{n0}) Y^{1/3}$$

$$b^* = 500 (b' - b'_{n0}) Y^{1/3}$$

$$a = a_2 [x/y + 1]$$

$$b = b_2 [z/y + 1/6]^{1/3}$$

$$a_2 = 1/15 = 0.06666$$

$$b_2 = -1/12 = -0.08333$$

$$n = P00$$

LABHNU1 79

Name und Farbart

$$R_{d,sRGB} \quad x=0,64 \quad y=0,33$$

$$G_{d,sRGB} \quad x=0,30 \quad y=0,60$$

$$B_{d,sRGB} \quad x=0,18 \quad y=0,06$$

Geräte- & Elementarfärbungen, $Y_W=100$


des sRGB-Farbenraums für P00

in Buntheitsdiagramm (A^* , B^*)

B^*

B^*

Parameter: c_{ab}



$XYZ_w=97.65, 100.0, 118.42$

$a^* = 500 (a' - a'_{n}) Y^{1/3}$

$b^* = 500 (b' - b'_{n}) Y^{1/3}$


$a = a_2 [x/y + 1]$

$b = b_2 [z/y + 1/6]^{1/3}$

$a_2 = 1/15 = 0.06666$

$b_2 = -1/12 = -0.08333$

$n = Q00$



LABHNU1 79

Name und Farbart

$R_{d,sRGB} \quad x=0,64 \quad y=0,33$

$G_{d,sRGB} \quad x=0,30 \quad y=0,60$

$B_{d,sRGB} \quad x=0,18 \quad y=0,06$

Geräte- & Elementarfärbungen, $Y_W=100$

des $sRGB$ -Farbenraums für Q00

in Buntheitsdiagramm (A^* , B^*)