



$L/\Delta L$ luminance contrast sensitivity threshold

• $L_g = 0,1 \text{ cd/m}^2$



$L/\Delta L$ luminance contrast sensitivity threshold

• $L_g = 1 \text{ cd/m}^2$




$L/\Delta L$ luminance contrast
sensitivity threshold

• $L_g = 10 \text{ cd/m}^2$


$x \quad y$
 $A \quad 0,39 \quad 0,41 \quad LI \quad 0,4s \quad A$
 $A1=108.4$ equation
 $A2=-0.99$
 $A3=1.0$
 $A4=0.33$

$$F = A1(F3'/F3 + F4'/F4); = L / \Delta L$$



$L/\Delta L$ luminance contrast
sensitivity threshold

• $L_g = 100 \text{ cd/m}^2$



$L/\Delta L$ luminance contrast
sensitivity threshold

• $L_g = 1000 \text{ cd/m}^2$

