

Güte (STRESS-Werte) für kleine (small) Farbdifferenzdaten (SCD)

iimp=100, WA=WANG colour difference pairs %

ia	d_rangeLAB	LABmin,max,mean	STRESS	CMCmin,max,mean	STRESS	C94min,max,mean	STRESS	C00min,max,mean	STRESS	C85min,max,mean	STRESS
100 100	0.0 to <99	0.19 1.35 0.54	33.2	0.21 0.69 0.39	23.0	0.15 0.73 0.38	30.9	0.19 0.51 0.36	18.0	0.54 5.82 2.85	45.7 %
100 100	0.0 to <5.0	0.19 1.35 0.54	33.2	0.21 0.69 0.39	23.0	0.15 0.73 0.38	30.9	0.19 0.51 0.36	18.0	0.54 5.82 2.85	45.7 %
100 46	0.0 to <0.5	0.19 0.49 0.39	32.0	0.21 0.64 0.38	23.2	0.15 0.49 0.34	26.7	0.19 0.51 0.35	14.9	0.54 5.35 2.69	43.2 %
100 53	0.5 to <1.0	0.5 0.94 0.66	32.0	0.24 0.69 0.4	23.1	0.22 0.73 0.42	27.2	0.22 0.49 0.36	15.4	0.91 5.82 3.0	45.1 %
100 1	1.0 to <1.5	1.35 1.35 0.1		0.52 0.52 0.52	0.1	0.42 0.42 0.42	0.1	0.41 0.41 0.41	0.1	1.88 1.88 1.88	0.1 %
100 0	1.5 to <2.0 %										
100 0	2.0 to <5.0 %										
100 0	5.0 to <10 %										
100 0	10 to <15 %										
100 0	15 to <20 %										
100 0	20 to <25 %										
100 0	25 to <30 %										
100 0	30 to <99 %										

iimp=100, WA=WANG colour difference pairs %

ia	d_rangeC00	LABmin,max,mean	STRESS	CMCmin,max,mean	STRESS	C94min,max,mean	STRESS	C00min,max,mean	STRESS	C85min,max,mean	STRESS
100 100	0.0 to <99	0.19 1.35 0.54	33.2	0.21 0.69 0.39	23.0	0.15 0.73 0.38	30.9	0.19 0.51 0.36	18.0	0.54 5.82 2.85	45.7 %
100 100	0.0 to <5.0	0.19 1.35 0.54	33.2	0.21 0.69 0.39	23.0	0.15 0.73 0.38	30.9	0.19 0.51 0.36	18.0	0.54 5.82 2.85	45.7 %
100 98	0.0 to <0.5	0.19 1.35 0.55	33.4	0.21 0.69 0.39	23.0	0.15 0.73 0.38	30.9	0.19 0.49 0.35	17.8	0.54 5.82 2.87	45.5 %
100 2	0.5 to <1.0	0.36 0.44 0.4	4.5	0.5 0.61 0.56	5.0	0.35 0.43 0.39	5.0	0.51 0.51 0.51	5.9	1.06 1.94 1.5	0.5 %
100 0	1.0 to <1.5 %										
100 0	1.5 to <2.0 %										
100 0	2.0 to <5.0 %										
100 0	5.0 to <10 %										
100 0	10 to <15 %										
100 0	15 to <20 %										
100 0	20 to <25 %										
100 0	25 to <30 %										
100 0	30 to <99 %										

iimp=100, WA=WANG colour difference pairs %

ia	d_rangeC85	LABmin,max,mean	STRESS	CMCmin,max,mean	STRESS	C94min,max,mean	STRESS	C00min,max,mean	STRESS	C85min,max,mean	STRESS
100 100	0.0 to <99	0.19 1.35 0.54	33.2	0.21 0.69 0.39	23.0	0.15 0.73 0.38	30.9	0.19 0.51 0.36	18.0	0.54 5.82 2.85	45.7 %
100 93	0.0 to <5.0	0.19 1.35 0.54	33.0	0.21 0.69 0.38	22.5	0.15 0.73 0.37	31.3	0.19 0.51 0.35	18.1	0.54 4.97 2.66	45.2 %
100 0	0.0 to <0.5 %										
100 9	0.5 to <1.0	0.19 0.67 0.38	13.8	0.21 0.46 0.36	20.0	0.15 0.35 0.28	14.7	0.22 0.44 0.35	8.5	0.54 0.98 0.89	51.5 %
100 12	1.0 to <1.5	0.29 0.74 0.49	26.5	0.24 0.5 0.39	18.5	0.22 0.41 0.31	27.2	0.22 0.51 0.35	9.0	1.06 1.45 1.23	48.4 %
100 17	1.5 to <2.0	0.34 1.35 0.63	29.4	0.28 0.69 0.49	23.8	0.23 0.44 0.36	30.1	0.23 0.51 0.37	9.8	1.53 1.97 1.77	49.3 %
100 55	2.0 to <5.0	0.3 0.94 0.55	31.9	0.22 0.49 0.36	23.1	0.19 0.73 0.41	27.2	0.19 0.49 0.35	15.2	2.0 4.97 3.54	46.0 %
100 7	5.0 to <10	0.46 0.7 0.54	13.0	0.41 0.56 0.48	18.7	0.45 0.7 0.53	13.6	0.36 0.49 0.41	9.1	5.17 5.82 5.32	53.9 %
100 0	10 to <15 %										
100 0	15 to <20 %										
100 0	20 to <25 %										
100 0	25 to <30 %										
100 0	30 to <99 %										