

Güte (STRESS-Werte) für kleine (small) Farbdifferenzdaten (SCD)

iimp=100, WA=WANG colour difference pairs %

ia	d_rangeLAB	LABmin,max,mean	STRESS	CMCmin,max,mean	STRESS	C94min,max,mean	STRESS	C00min,max,mean	STRESS	C85min,max,mean	STRESS												
100	100	0.0 to <99	0.19	1.35	0.54	33.2	0.21	0.69	0.39	23.0	0.15	0.73	0.38	30.9	0.19	0.51	0.36	18.0	0.54	5.82	2.85	45.7	%
100	100	0.0 to <5.0	0.19	1.35	0.54	33.2	0.21	0.69	0.39	23.0	0.15	0.73	0.38	30.9	0.19	0.51	0.36	18.0	0.54	5.82	2.85	45.7	%
100	46	0.0 to <0.5	0.19	0.49	0.39	32.0	0.21	0.64	0.38	23.2	0.15	0.49	0.34	26.7	0.19	0.51	0.35	14.9	0.54	5.35	2.69	43.2	%
100	53	0.5 to <1.0	0.5	0.94	0.66	32.0	0.24	0.69	0.4	23.1	0.22	0.73	0.42	27.2	0.22	0.49	0.36	15.4	0.91	5.82	3.0	45.1	%
100	1	1.0 to <1.5	1.35	1.35	0.1	0.52	0.52	0.52	0.1	0.42	0.42	0.42	0.1	0.41	0.41	0.41	0.1	1.88	1.88	1.88	0.1	%	
100	0	1.5 to <2.0	%																				
100	0	2.0 to <5.0	%																				
100	0	5.0 to <10	%																				
100	0	10 to <15	%																				
100	0	15 to <20	%																				
100	0	20 to <25	%																				
100	0	25 to <30	%																				
100	0	30 to <99	%																				

iimp=100, WA=WANG colour difference pairs %

		d_rangeC00	LABmin,max,mean STRESS				CMCmin,max,mean STRESS				C94min,max,mean STRESS				C00min,max,mean STRESS				C85min,max,mean STRESS			
100	100	0.0 to <99	0.19	1.35	0.54	33.2	0.21	0.69	0.39	23.0	0.15	0.73	0.38	30.9	0.19	0.51	0.36	18.0	0.54	5.82	2.85	45.7
100	100	0.0 to <5.0	0.19	1.35	0.54	33.2	0.21	0.69	0.39	23.0	0.15	0.73	0.38	30.9	0.19	0.51	0.36	18.0	0.54	5.82	2.85	45.7
100	98	0.0 to <0.5	0.19	1.35	0.55	33.4	0.21	0.69	0.39	23.0	0.15	0.73	0.38	30.9	0.19	0.49	0.35	17.8	0.54	5.82	2.87	45.5
100	2	0.5 to <1.0	0.36	0.44	0.4	4.5	0.5	0.61	0.56	5.0	0.35	0.43	0.39	5.0	0.51	0.51	0.51	5.9	1.06	1.94	1.5	0.5 %
100	0	1.0 to <1.5	%																			
100	0	1.5 to <2.0	%																			
100	0	2.0 to <5.0	%																			
100	0	5.0 to <10	%																			
100	0	10 to <15	%																			
100	0	15 to <20	%																			
100	0	20 to <25	%																			
100	0	25 to <30	%																			
100	0	30 to <99	%																			

iimp=100, WA=WANG colour difference pairs %

ia	d_rangeC85	LABmin,max,mean	STRESS	CMCmin,max,mean	STRESS	C94min,max,mean	STRESS	C00min,max,mean	STRESS	C85min,max,mean	STRESS											
100	100	0.0 to <99	0.19	1.35	0.54	33.2	0.21	0.69	0.39	23.0	0.15	0.73	0.38	30.9	0.19	0.51	0.36	18.0	0.54	5.82	2.85	45.7
100	93	0.0 to <5.0	0.19	1.35	0.54	33.0	0.21	0.69	0.38	22.5	0.15	0.73	0.37	31.3	0.19	0.51	0.35	18.1	0.54	4.97	2.66	45.2
100	0	0.0 to <0.5	%																			
100	9	0.5 to <1.0	0.19	0.67	0.38	13.8	0.21	0.46	0.36	20.0	0.15	0.35	0.28	14.7	0.22	0.44	0.35	8.5	0.54	0.98	0.89	51.5
100	12	1.0 to <1.5	0.29	0.74	0.49	26.5	0.24	0.5	0.39	18.5	0.22	0.41	0.31	27.2	0.22	0.51	0.35	9.0	1.06	1.45	1.23	48.4
100	17	1.5 to <2.0	0.34	1.35	0.63	29.4	0.28	0.69	0.49	23.8	0.23	0.44	0.36	30.1	0.23	0.51	0.37	9.8	1.53	1.97	1.77	49.3
100	55	2.0 to <5.0	0.3	0.94	0.55	31.9	0.22	0.49	0.36	23.1	0.19	0.73	0.41	27.2	0.19	0.49	0.35	15.2	2.0	4.97	3.54	46.0
100	7	5.0 to <10	0.46	0.7	0.54	13.0	0.41	0.56	0.48	18.7	0.45	0.7	0.53	13.6	0.36	0.49	0.41	9.1	5.17	5.82	5.32	53.9
100	0	10 to <15	%																			
100	0	15 to <20	%																			
100	0	20 to <25	%																			
100	0	25 to <30	%																			
100	0	30 to <99	%																			

Siehe ähnliche Dateien: <http://130.149.60.45/~farbmetrik/VG91/VG91L0N1.TXT> /PS
Technische Information: <http://www.ps.bam.de> oder <http://130.149.60.45/~farbmetrik>

TUB-Registrierung: 20140801-VG91/VG91L0N1.TXT /PS
Anwendung für Messung von Display- oder Drucker-Ausgabe

TUB-Material: Code=th44a