

www.ps.bam.de/DE49/10Q/Q49E00NA.PS/.TXT; start output with no LAB* transfer and no OL
N: No Output Linearization (OL) data in File (F), Startup (S) or Device (D)




Figure B4 and/or D4 of the ISO/IEC-test charts; $w^* - cmy^*$; $w^* - olv(cmy)^*$; 16 visual equidistant steps of colour series: $LAB^* \rightarrow \Delta LAB^*$; LM methods: N, F, S, D, T, E

16 colours according to ISO/IEC 15775 and 19839-X; setcolor -> setcmykcolor, but NO setgray