




Radial grating (Siemens-star) N-W



Radial grating (Siemens-star) W-N



Radial grating (Siemens-star) N-Z



Radial grating (Siemens-star) W-Z



Picture C1: Radial gratings (Siemens-stars) N-W, W-N, N-Z and W-Z; Use of the PS operator *LAB* setcolor*Picture C2: 5 visual equidistant L^* -grey steps + N_0 + W_1 ; Use of the PS operator *LAB* setcolor*Picture C3: 16 visual equidistant L^* -grey steps; Use of the PS operator *LAB* setcolor*

Fig. A1 to A6 of ISO/IEC-test chart 1;

ISO/IEC 15775 and
DIS ISO/IEC 19839-X;input: mixture (m) of PS operators
output: *Startup (S)* data dependentbackground step 0
Hex code

7

E

2

8

F

1 ring step
Hex code

8

F

0

6

D

0-1

7-8

E-F



2-0

8-6

F-D

Landolt-rings W-N

code: background-ring

Picture C4: Landolt-rings W-N; Use of the PS operator *LAB* setcolor*Picture C5: Line raster under 45° (or 135°); Use of the PS operator *LAB* setcolor*Picture C6: Line raster under 90° (or 0°); Use of the PS operator *LAB* setcolor*