





Picture D1: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (nf); PS operators *settransfer*, 3 *colorimage*




Picture D2: Radial gratings W-O, W-L, W-V, W-N, and W-Z; PS operator *olv* setrgbcolor (only)*




Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *olv* setrgbcolor (only)*

Fig. D1 to D7 of ISO/IEC-test chart 4;

ISO/IEC 15775 and
 DIS ISO/IEC 19839-X; output: *LAB* setcolor*




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator *olv* setrgbcolor (only)*



Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator *olv* setrgbcolor (only)*



Picture D6: Landolt-rings W-O and W-L; Use of PS operator *olv* setrgbcolor (only)*



Picture D7: Landolt-rings W-V and W-N; Use of PS operator *olv* setrgbcolor (only)*

BAM registration: 20030101-DE99/10L/L99E05FP.PS./PDF BAM material: code=rha4ta
 application for monitors (Yr=2.5) and printers