





Picture D1: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (nf); PS operators *settransfer*, 4 *colorimage*




Picture D2: Radial gratings W-O, W-L, W-V, W-N, and W-Z; PS operator *cmy0* setcmykcolor (only)*



Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *cmy0* setcmykcolor (only)*

Fig. D1 to D7 of ISO/IEC-test chart 4;


ISO/IEC 15775 and
DIS ISO/IEC 19839-X; output: *LAB* setcolor*




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator *cmy0* setcmykcolor (only)*

+:-.	O	O	O	O	lmno	O	O	O	pqrs	O	O	O	tuvw	O	O	O
xyz;	O	O	O	O	hijk	O	O	O	lmno	O	O	O	lmno	O	O	O
tuvw	O	O	O	O	defg	O	O	O	hijk	O	O	O	hijk	O	O	O
pqrs	O	O	O	O	!abc	O	O	O	defg	O	O	O	defg	O	O	O
lmno	O	O	O	O	+:-.	O	O	O	!abc	O	O	O	!abc	O	O	O
hijk	O	O	O	O	xyz;	O	O	O	tuvw	O	O	O	xyz;	O	O	O
defg	O	O	O	O	tuvw	O	O	O	defg	O	O	O	defg	O	O	O
!abc	O	O	O	O	pqrs	O	O	O	!abc	O	O	O	!abc	O	O	O
10 N O L V					8 N O L V				8 N O L V				6 N O L V			

Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator *cmy0* setcmykcolor (only)*



Picture D6: Landolt-rings W-O and W-L; Use of PS operator *cmy0* setcmykcolor (only)*



Picture D7: Landolt-rings W-V and W-N; Use of PS operator *cmy0* setcmykcolor (only)*

BAM registration: 20030101-EE98/10L/L98E05FP.PS/.PDF BAM material: code=rha4ta application for monitors (Yr=2.5) and printers