





Picture D1: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (nf); PS operators *settransfer*, 3 *colorimage*




Picture D2: Radial gratings W-O, W-L, W-V, W-N, and W-Z; PS operator *olv\* setrgbcolor (only)*



Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *olv\* setrgbcolor (only)*

Fig. D1 to D7 of ISO/IEC-test chart 4;


ISO/IEC 15775 and  
DIS ISO/IEC 19839-X; output: *w\* setgray*




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator *olv\* setrgbcolor (only)*

+:-.	O	O	O	O	lmno	O	O	O	pqrs	O	O	O	tuvw	O	O	O			
xyz;	O	O	O	O	hijk	O	O	O	lmno	O	O	O	xyz;	O	O	O			
tuvw	O	O	O	O	defg	O	O	O	hijk	O	O	O	tuvw	O	O	O			
pqrs	O	O	O	O	!abc	O	O	O	defg	O	O	O	defg	O	O	O			
lmno	O	O	O	O	+:-.	O	O	O	!abc	O	O	O	!abc	O	O	O			
hijk	O	O	O	O	xyz;	O	O	O	tuvw	O	O	O	xyz;	O	O	O			
defg	O	O	O	O	defg	O	O	O	defg	O	O	O	defg	O	O	O			
!abc	O	O	O	O	+:-.	O	O	O	!abc	O	O	O	!abc	O	O	O			
10	N	O	L	V	10	N	O	L	V	8	N	O	L	V	6	N	O	L	V

Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator *olv\* setrgbcolor (only)*



Picture D6: Landolt-rings W-O and W-L; Use of PS operator *olv\* setrgbcolor (only)*



Picture D7: Landolt-rings W-V and W-N; Use of PS operator *olv\* setrgbcolor (only)*

BAM registration: 20030101-EE99/10L/L99E07FP.PS/.PDF BAM material: code=rha4ta  
application for monitors (Yr=2.5) and printers