


Picture D2: Radial gratings **W-O**, **W-L**, **W⁻V**, **W-N**, and **W-Z**; Use of PS operator **LAB* setcolor**



Picture B3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *LAB* setcolor*

Fig. D1 to D7 of ISO/IEC-test chart 4;



ISO/IEC 15775 and input: *LAB* setcolor*
DIS ISO/IEC 19839-X; output: *Startup (S) data dependend*



Picture D4: 16 equidistant steps *W-O*, *W-L*, *W-V* and *W-N*; Use of PS operator *LAB* setcolor*



Picture D5: Script and Landolt-rings *N*, *O*, *L* and *V*; Use of PS operator *LAB* setcolor*

Picture D6: Landolt-rings **W-O** and **W-L**; Use of PS operator *LAB* setcolor*Picture D7: Landolt-rings W-V and W-N; Use of PS operator *LAB* setcolor*