





Picture D1: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (nf); PS operators *settransfer*, *3 colorimage*



Radial grating W-O Radial grating W-L Radial grating W-V Radial grating W-N Radial grating W-Z


Picture D2: Radial gratings W-O, W-L, W-V, W-N, and W-Z; PS operator *olv\* setrgbcolor (only)*




Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *olv\* setrgbcolor (only)*

Fig. D1 to D7 of ISO/IEC-test chart 4;


ISO/IEC 15775 and  
DIS ISO/IEC 19839-X; output: *w\* setgray*




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator *olv\* setrgbcolor (only)*



Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator *olv\* setrgbcolor (only)*



Picture D6: Landolt-rings W-O and W-L; Use of PS operator *olv\* setrgbcolor (only)*



Picture D7: Landolt-rings W-V and W-N; Use of PS operator *olv\* setrgbcolor (only)*

