





Picture D1: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (nf); PS operators *settransfer*, 4 *colorimage*




Picture D2: Radial gratings W-O, W-L, W-V, W-N, and W-Z; PS operator *cmy0\* setcmykcolor (only)*



Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *cmy0\* setcmykcolor (only)*

Fig. D1 to D7 of ISO/IEC-test chart 4;

ISO/IEC 15775 and  
DIS ISO/IEC 19839-X; output: *lab\* setcolor*




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator *cmy0\* setcmykcolor (only)*


+:-.	O	O	O	O	lmno	O	O	O	pqrs	O	O	O	tuvw	O	O	O	
xyz;	O	O	O	O	hijk	O	O	O	lmno	O	O	O	xyz;	O	O	O	
tuvw	O	O	O	O	defg	O	O	O	hijk	O	O	O	tuvw	O	O	O	
pqrs	O	O	O	O	!abc	O	O	O	defg	O	O	O	defg	O	O	O	
lmno	O	O	O	O	+:-.	O	O	O	!abc	O	O	O	!abc	O	O	O	
hijk	O	O	O	O	xyz;	O	O	O	xyz;	O	O	O	xyz;	O	O	O	
defg	O	O	O	O	tuvw	O	O	O	tuvw	O	O	O	tuvw	O	O	O	
!abc	O	O	O	O	pqrs	O	O	O	defg	O	O	O	defg	O	O	O	
10	N	O	L	V	10	N	O	L	V	6	N	O	L	V	6	N	O

tuvw  
pqrs  
lmno  
hijk  
+:-.  
!abc  
xyz;  
tuvw  
defg  
!abc  
6 N O L V

Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator *cmy0\* setcmykcolor (only)*



Picture D6: Landolt-rings W-O and W-L; Use of PS operator *cmy0\* setcmykcolor (only)*



Picture D7: Landolt-rings W-V and W-N; Use of PS operator *cmy0\* setcmykcolor (only)*