



Picture D4n: 16 equidistant steps W-O, W-L, W-V and W-N; PS operator LAB* setcolor




Picture D5n: Script and Landolt-rings W, O, L and V; PS operator LAB* setcolor




Picture D6n: Landolt-rings N-O and N-L; PS operator LAB* setcolor




Picture D7n: Landolt-rings N-V and N-N; PS operator LAB* setcolor




Test chart LE32: 16 CIELAB steps of ISO/IEC 15775
Chromatic-White, Chromatic-Black, Black-White




Picture D4w: 16 equidistant steps W-O, W-L, W-V and W-N; PS operator LAB* setcolor




Picture D5w: Script and Landolt-rings N, O, L and V; PS operator LAB* setcolor



Picture D6w: Landolt-rings W-O and W-L; PS operator LAB* setcolor



Picture D7w: Landolt-rings W-V and W-N; PS operator LAB* setcolor



input(TLS00): LAB* setcolor
output(TLS00): no change compared to input