

# Linear relation CIELAB ( $L^*, a^*, b^*$ ) and adapted (a) CIELAB ( $C^*_{ab,a}, L^*$ )

System: Laser printer


$$l^*_{lab*} = (L^* - L^*_N) / (L^*_W - L^*_N)$$

$$a^*_{ab} = a^* - a^*_N - l^*_{lab*} [a^*_W - a^*_N]$$

$$b^*_{ab} = b^* - b^*_N - l^*_{lab*} [b^*_W - b^*_N]$$

CIELAB hue angles:

$$h_{ab} = [40, 101, 142, 227, 276, 355]$$



Linear relation CIELAB ( $L^*, a^*, b^*$ ) and adapted (a) CIELAB ( $C^*_{ab,a}, L^*$ )

System: Laser printer


$$l^*_{lab*} = (L^* - L^*_N) / (L^*_W - L^*_N)$$

$$a^*_{ab} = a^* - a^*_N - l^*_{lab*} [a^*_W - a^*_N]$$

$$b^*_{ab} = b^* - b^*_N - l^*_{lab*} [b^*_W - b^*_N]$$

CIELAB hue angles:

$$h_{ab} = [33, 100, 149, 252, 300, 350]$$



Linear relation CIELAB ( $L^*, a^*, b^*$ ) and adapted (a) CIELAB ( $C^*_{ab,a}, L^*$ )

System: Laser printer


$$l^*_{lab*} = (L^* - L^*_N) / (L^*_W - L^*_N)$$

$$a^*_{ab} = a^* - a^*_N - l^*_{lab*} [a^*_W - a^*_N]$$

$$b^*_{ab} = b^* - b^*_N - l^*_{lab*} [b^*_W - b^*_N]$$

CIELAB hue angles:

$$h_{ab} = [40, 100, 146, 246, 297, 355]$$



Linear relation CIELAB ( $L^*, a^*, b^*$ ) and adapted (a) CIELAB ( $C^*_{ab,a}, L^*$ )

System: Laser printer


$$l^*_{lab*} = (L^* - L^*_N) / (L^*_W - L^*_N)$$

$$a^*_{ab} = a^* - a^*_N - l^*_{lab*} [a^*_W - a^*_N]$$

$$b^*_{ab} = b^* - b^*_N - l^*_{lab*} [b^*_W - b^*_N]$$

CIELAB hue angles:

$$h_{ab} = [39, 100, 147, 246, 297, 355]$$



# Linear relation CIELAB ( $L^*, a^*, b^*$ ) and adapted (a) CIELAB ( $C^*_{ab,a}, L^*$ )

System: Laser printer


$$l^*_{lab*} = (L^* - L^*_N) / (L^*_W - L^*_N)$$

$$a^*_{ab} = a^* - a^*_N - l^*_{lab*} [a^*_W - a^*_N]$$

$$b^*_{ab} = b^* - b^*_N - l^*_{lab*} [b^*_W - b^*_N]$$

CIELAB hue angles:

$$h_{ab} = [38, 99, 146, 230, 280, 357]$$



Linear relation CIELAB ( $L^*, a^*, b^*$ ) and adapted (a) CIELAB ( $C^*_{ab,a}, L^*$ )

System: Laser printer


$$l^*_{lab*} = (L^* - L^*_N) / (L^*_W - L^*_N)$$

$$a^*_{ab} = a^* - a^*_N - l^*_{lab*} [a^*_W - a^*_N]$$

$$b^*_{ab} = b^* - b^*_N - l^*_{lab*} [b^*_W - b^*_N]$$

CIELAB hue angles:

$$h_{ab} = [32, 99, 153, 254, 303, 354]$$



Linear relation CIELAB ( $L^*, a^*, b^*$ ) and adapted (a) CIELAB ( $C^*_{ab,a}, L^*$ )

System: Laser printer


$$l^*_{lab*} = (L^* - L^*_N) / (L^*_W - L^*_N)$$

$$a^*_{ab} = a^* - a^*_N - l^*_{lab*} [a^*_W - a^*_N]$$

$$b^*_{ab} = b^* - b^*_N - l^*_{lab*} [b^*_W - b^*_N]$$

CIELAB hue angles:

$$h_{ab} = [39, 99, 151, 247, 299, 358] \quad Y \quad 100 \quad C^*_{ab,a} = [a^*_{ab} + b^*_{ab}]^{1/2}$$



Linear relation CIELAB ( $L^*, a^*, b^*$ ) and adapted (a) CIELAB ( $C^*_{ab,a}, L^*$ )

System: Laser printer

$$l^*_{lab*} = (L^* - L^*_N) / (L^*_W - L^*_N)$$

$$a^*_{ab} = a^* - a^*_N - l^*_{lab*} [a^*_W - a^*_N]$$

$$b^*_{ab} = b^* - b^*_N - l^*_{lab*} [b^*_W - b^*_N]$$

CIELAB hue angles:

$$h_{ab} = [40, 99, 151, 247, 299, 359] \quad Y \quad 100 \quad C^*_{ab,a} = [a^*_{ab} + b^*_{ab}]^{1/2}$$

