





AE180-3, Picture D1W*dd: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (sf); PS operators *settransfer*, 3 colorimage




AE180-5, Picture D2W*dd: radial gratings W-Rd; W-Gd; W-Bd; W-N; PS operator *rgb*->*rgb*dd* *setrgbcolor*




AE180-7, Picture D3W*dd: 14 CIE-test colours and 2 + 16 grey steps (sf); *rgb/cmy0*->*rgb*dd* *setrgbcolor*




AE181-1, Picture D4W*dd: 16 equidistant steps W-Rd; W-Gd; W-Bd; W-N; *rgb/cmy0*->*rgb*dd* *setrgbcolor*



AE181-3, Picture D5W*dd: Sript and Landolt-rings N; Rd; Gd; Bd; Z; PS operator *rgb*->*rgb*dd* *setrgbcolor*



AE181-5, Picture D6W*dd: Landolt-rings W-Rd; W-Gd; PS operator *rgb*->*rgb*dd* *setrgbcolor*



AE181-7, Picture D7W*dd: Landolt-rings W-Bd; W-N; PS operator *rgb*->*rgb*dd* *setrgbcolor*

input: *rgb/cmy0/000n/w* set...
output: ->*rgb*dd* *setrgbcolor*