




AE180-3, Picture D1W\*dd: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (sf); PS operators *settransfer*, 3 colorimage




radial gratings  $W-R_d$  radial gratings  $W-G_d$  radial gratings  $W-B_d$  radial gratings  $W-N$  radial gratings  $W-Z$


AE180-5, Picture D2W\*dd: radial gratings  $W-R_d$ ;  $W-G_d$ ;  $W-B_d$ ;  $W-N$ ; PS operator *rgb*->*rgb\*dd* *setrgbcolor*




AE180-7, Picture D3W\*dd: 14 CIE-test colours and 2 + 16 grey steps (sf); *rgb/cmy0*->*rgb\*dd* *setrgbcolor*




Test chart AE18 according to test chart 4 of ISO/IEC 15775  
chromatic test chart RGB




AE181-1, Picture D4W\*dd: 16 equidistant steps  $W-R_d$ ;  $W-G_d$ ;  $W-B_d$ ;  $W-N$ ; *rgb/cmy0*->*rgb\*dd* *setrgbcolor*



AE181-3, Picture D5W\*dd: Sript and Landolt-rings  $N$ ;  $R_d$ ;  $G_d$ ;  $B_d$ ;  $Z$ ; PS operator *rgb*->*rgb\*dd* *setrgbcolor*



AE181-5, Picture D6W\*dd: Landolt-rings  $W-R_d$ ;  $W-G_d$ ; PS operator *rgb*->*rgb\*dd* *setrgbcolor*



AE181-7, Picture D7W\*dd: Landolt-rings  $W-B_d$ ;  $W-N$ ; PS operator *rgb*->*rgb\*dd* *setrgbcolor*

input: *rgb/cmy0/000n/w* *set...*  
output: ->*rgb\*dd* *setrgbcolor*