


input: 000n / w / nnn0 / www set...
output: no change compared to input

See for similar files: <http://www.ps.bam.de/Ee48/>; www.ps.bam.de
Technical information: <http://www.ps.bam.de>
Version 2.1, io=1,1, ColSpx=0

www.ps.bam.de/Ee48/10L/L48E00NP.PS/.PDF; FRS09_92aM; transfer and output
N: No Output Linearization (OL) data in File (F), Startup (S) or Device (D)




BAM-test chart Ee48; Colorimetric systems, Page 2/11
D65: colour scales and 9 tables for 16 hues o00y to y51

input: 000n / w / nnn0 / www set..
output: ->cmY0* setcmYkcolor

BAM registration: 20080901-Ee48/10L/L48E00NP.PS/.PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=rha4ta

```
input: 000n / w / nnn0 / www set...
output: ->cmy0* setcmykcolor
```




See for similar files: <http://www.ps.bam.de/Ee48/>; www.ps.bam.de/Ee.HTM
 Technical information: <http://www.ps.bam.de> Version 2.1, io=1,1, ColSpx=0




BAM registration: 20080901-EE48/10/L/48E00NP.PS/.PDF BAM material application for evaluation and measurement of printer or monitor systems

```
input: 000n / w / nnn0 / www set...
output: ->cmv0* setcmvcolor
```



See for similar files: <http://www.ps.bam.de/Ee48/>; www.ps.bam.de/Version2.1,io=1.1,Colspx=0




www.ps.bam.de/Ee48/10L/L48E00NP.PS/.PDF; FRS09_92aM; transfer and output
N: No Output Linearization (OL) data in File (F), Startup (S) or Device (D)



BAM registration: 20080901-Ee48/10L/L48E00NP.PS/.PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=rha4ta



BAM-test chart Ee48; Colorimetric systems, Page 10/11
D65: colour scales and 9 tables for 16 hues o00y to y75l

input: 000n / w / nnn0 / www set...
output: ->cmY0* setcmYkcolor

