







Fe021-1, Picture D4: 16 equidistant steps *W-O*, *W-L*, *W-V*, *W-N*; PS operator *olv* setrgbcolor*




Fe021-3, Picture D5: Script and Landolt-rings *N*, *O*, *L*, *V*, *Z*; PS operator *olv* setrgbcolor*




Fe020-5, Picture D2: Radial gratings *W-O*, *W-L*, *W-V*, *W-N*, *W-Z*; PS operator *olv* setrgbcolor*




Fe020-7, Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *olv* setrgbcolor*




Fe021-5, Picture D6: Landolt-rings *W-O*, *W-L*; PS operator *olv* setrgbcolor*




Fe021-7, Picture D7: Landolt-rings *W-V*, *W-N*; PS operator *olv* setrgbcolor*




Fe021-1, Picture D4: 16 equidistant steps *W-O*, *W-L*, *W-V*, *W-N*; PS operator *olv* setrgbcolor*




Fe021-3, Picture D5: Script and Landolt-rings *N*, *O*, *L*, *V*, *Z*; PS operator *olv* setrgbcolor*




Fe020-5, Picture D2: Radial gratings *W-O*, *W-L*, *W-V*, *W-N*, *W-Z*; PS operator *olv* setrgbcolor*



Fe020-7, Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator *olv* setrgbcolor*



Fe021-5, Picture D6: Landolt-rings *W-O*, *W-L*; PS operator *olv* setrgbcolor*



Fe021-7, Picture D7: Landolt-rings *W-V*, *W-N*; PS operator *olv* setrgbcolor*

