

HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{F02_X,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{P60: } \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 98,26$$

$$x_{\text{F02_X,s}} = 0,2218$$

$$y_{\text{F02_X,s}} = 0,2646$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{F02_X,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{P55: } \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 98,31$$

$$x_{\text{F02_X,s}} = 0,2303$$

$$y_{\text{F02_X,s}} = 0,2772$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{F02_X,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{P50: } \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 98,50$$

$$x_{\text{F02_X,s}} = 0,2413$$

$$y_{\text{F02_X,s}} = 0,2923$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{F02_X,s}}(\lambda)$$

$\mathbf{B}_{1j}$ 0,2105 0,8550 -0,0396 $\lambda=570$

P45: $\Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 98,91$

$x_{\text{F02_X,s}} = 0,2556$

$y_{\text{F02_X,s}} = 0,3105$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{F02_X,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{P40: } \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 99,71$$

$$x_{\text{F02_X,s}} = 0,2749$$

$$y_{\text{F02_X,s}} = 0,3325$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{l}_{\text{F02_X,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{F02_X,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{P35: } \Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 101,20$$

$$x_{\text{F02_X,s}} = 0,3012$$

$$y_{\text{F02_X,s}} = 0,3584$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{l}_{\text{F02_X,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{F02_X,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{P30: } \Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 103,98$$

$$x_{\text{F02_X,s}} = 0,3376$$

$$y_{\text{F02_X,s}} = 0,3877$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$

$$\bar{l}_{\text{F02_X,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{F02_X,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{F02_X,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{P25: } \Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 109,46$$

$$x_{\text{F02_X,s}} = 0,3880$$

$$y_{\text{F02_X,s}} = 0,4168$$

