

HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X,s}}(\lambda) = B_{31}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{32}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{33}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$\text{P60: } \Sigma \bar{s}_{\text{F02_X,s}}(\lambda) = 103,18$$

$$x_{\text{F02_X,s}} = 0,2218$$

$$y_{\text{F02_X,s}} = 0,2646$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X,s}}(\lambda) = B_{31}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{32}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{33}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$P55: \Sigma \bar{s}_{\text{F02_X,s}}(\lambda) = 94,02$$

$$x_{\text{F02_X,s}} = 0,2303$$

$$y_{\text{F02_X,s}} = 0,2772$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X,s}}(\lambda) = B_{31}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{32}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{33}\bar{z}_{\text{F02_X,s}}(\lambda)$$

B_{3j} 0,000 0,000 0,5168 $\lambda=440$

P50: $\Sigma \bar{s}_{\text{F02_X,s}}(\lambda) = 84,08$

$x_{\text{F02_X,s}} = 0,2413$

$y_{\text{F02_X,s}} = 0,2923$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X,s}}(\lambda) = B_{31}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{32}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{33}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$P45: \Sigma \bar{s}_{\text{F02_X,s}}(\lambda) = 73,36$$

$$x_{\text{F02_X,s}} = 0,2556$$

$$y_{\text{F02_X,s}} = 0,3105$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{F02_X,s}(\lambda) = B_{31}\bar{x}_{F02_X,s}(\lambda) + B_{32}\bar{y}_{F02_X,s}(\lambda) + B_{33}\bar{z}_{F02_X,s}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$P40: \Sigma \bar{s}_{F02_X,s}(\lambda) = 61,93$$

$$x_{F02_X,s} = 0,2749$$

$$y_{F02_X,s} = 0,3325$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X,s}}(\lambda) = B_{31}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{32}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{33}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$P35: \Sigma \bar{s}_{\text{F02_X,s}}(\lambda) = 49,93$$

$$x_{\text{F02_X,s}} = 0,3012$$

$$y_{\text{F02_X,s}} = 0,3584$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$


$$\bar{s}_{\text{F02_X,s}}(\lambda) = B_{31}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{32}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{33}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$P30: \Sigma \bar{s}_{\text{F02_X,s}}(\lambda) = 37,66$$

$$x_{\text{F02_X,s}} = 0,3376$$

$$y_{\text{F02_X,s}} = 0,3877$$



HPE_CIEF cone sensitivity $Y_{\text{sum}}=100$

$$\bar{s}_{\text{F02_X,s}}(\lambda) = B_{31}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{32}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{33}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{3j} \quad 0,000 \quad 0,000 \quad 0,5168 \quad \lambda=440$$

$$P25: \Sigma \bar{s}_{\text{F02_X,s}}(\lambda) = 25,64$$

$$x_{\text{F02_X,s}} = 0,3880$$

$$y_{\text{F02_X,s}} = 0,4168$$

