

LMS_R17M6 cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{R17M6,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{R17M6,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{R17M6,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{R17M6,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2564 \quad 0,6666 \quad -0,1794 \quad \lambda=570$$

$$\text{D65: } \Sigma \bar{I}_{\text{R17M6,s}}(\lambda) = 96,92$$

$$x_{\text{R17M6,s}} = 0,4837$$

$$y_{\text{R17M6,s}} = 0,2508$$



LMS_R17M6 cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{R17M6},s}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{R17M6},s}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{R17M6},s}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{R17M6},s}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2564 \quad 0,6666 \quad -0,1794 \quad \lambda=570$$

$$\text{D50: } \Sigma \bar{I}_{\text{R17M6},s}(\lambda) = 98,36$$

$$x_{\text{R17M6},s} = 0,5090$$

$$y_{\text{R17M6},s} = 0,2706$$



LMS_R17M6 cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{R17M6,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{R17M6,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{R17M6,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{R17M6,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2564 \quad 0,6666 \quad -0,1794 \quad \lambda=570$$

$$\text{P40: } \Sigma \bar{I}_{\text{R17M6,s}}(\lambda) = 100,99$$

$$x_{\text{R17M6,s}} = 0,5362$$

$$y_{\text{R17M6,s}} = 0,2797$$



LMS_R17M6 cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{R17M6},s}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{R17M6},s}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{R17M6},s}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{R17M6},s}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2564 \quad 0,6666 \quad -0,1794 \quad \lambda=570$$

$$A00: \Sigma \bar{I}_{\text{R17M6},s}(\lambda) = 107,67$$

$$x_{\text{R17M6},s} = 0,5892$$

$$y_{\text{R17M6},s} = 0,2978$$



LMS_R17M6 cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{R17M6},s}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{R17M6},s}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{R17M6},s}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{R17M6},s}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2564 \quad 0,6666 \quad -0,1794 \quad \lambda=570$$

$$\text{E00: } \Sigma \bar{I}_{\text{R17M6},s}(\lambda) = 99,94$$

$$x_{\text{R17M6},s} = 0,4999$$

$$y_{\text{R17M6},s} = 0,2500$$



LMS_R17M6 cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{R17M6,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{R17M6,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{R17M6,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{R17M6,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2564 \quad 0,6666 \quad -0,1794 \quad \lambda=570$$

$$\text{C00: } \Sigma \bar{I}_{\text{R17M6,s}}(\lambda) = 98,16$$

$$x_{\text{R17M6,s}} = 0,4836$$

$$y_{\text{R17M6,s}} = 0,2428$$



LMS_R17M6 cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{R17M6},s}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{R17M6},s}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{R17M6},s}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{R17M6},s}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2564 \quad 0,6666 \quad -0,1794 \quad \lambda=570$$

$$\text{P00: } \Sigma \bar{I}_{\text{R17M6},s}(\lambda) = 101,73$$

$$x_{\text{R17M6},s} = 0,5209$$

$$y_{\text{R17M6},s} = 0,2632$$



LMS_R17M6 cone sensitivity $Y_{\text{sum}}=100$

$$\bar{I}_{\text{R17M6,s}}(\lambda) = \mathbf{B}_{11} \bar{x}_{\text{R17M6,s}}(\lambda) + \mathbf{B}_{12} \bar{y}_{\text{R17M6,s}}(\lambda) + \mathbf{B}_{13} \bar{z}_{\text{R17M6,s}}(\lambda)$$

$$\mathbf{B}_{1j} \quad 0,2564 \quad 0,6666 \quad -0,1794 \quad \lambda=570$$

$$Q00: \Sigma \bar{I}_{\text{R17M6,s}}(\lambda) = 98,67$$

$$x_{\text{R17M6,s}} = 0,4798$$

$$y_{\text{R17M6,s}} = 0,2344$$

