

Recommendation: Measure the larger adjacent samples!



$x_{B31} = 6,85 \text{ mm}$, $y_{B31} = 25,35 \text{ mm}$, $xd_{B31} = 7,7 \text{ mm}$



$x_{B32} = 6,85 \text{ mm}$, $y_{B32} = 13,35 \text{ mm}$, $xd_{B32} = 7,7 \text{ mm}$

$x_{B3} = 28 \text{ mm}$, $y_{B3} = 21 \text{ mm}$, $xd_{B3} = 130 \text{ mm}$, $yd_{B3} = 40 \text{ mm}$

Picture B3 or D3