

sensibilità relativa

$$\log V = [c \cdot \lambda - c \cdot 555]^2$$

... sperimentali CIE


P, D, T, V, V'

$$\log P = [c \cdot \lambda - c \cdot 570]^2$$

$$\log D = [c \cdot \lambda - c \cdot 540]^2$$

$$\log T = [c \cdot \lambda - c \cdot 450]^2$$

modello λ



4-003130-L0

4-003130-F0

ME100-54/MI490-50

sensibilità relativa

$$\log V = [c \cdot \lambda - c \cdot 555]^2$$

... sperimentali CIE


P, D, T, V, V'

$$\log P = [c \cdot \lambda - c \cdot 570]^2$$

$$\log D = [c \cdot \lambda - c \cdot 540]^2$$

$$\log T = [c \cdot \lambda - c \cdot 450]^2$$

modello λ



4-013130-L0

4-013130-F0

ME100-54/MI490-51

sensibilità relativa

$$\log V = [c \cdot \lambda - c \cdot 555]^2$$

... sperimentali CIE


P, D, T, V, V'

$$\log P = [c \cdot \lambda - c \cdot 570]^2$$

$$\log D = [c \cdot \lambda - c \cdot 540]^2$$

$$\log T = [c \cdot \lambda - c \cdot 450]^2$$

modello λ



sensibilità relativa

$$\log V = [c \cdot \lambda - c \cdot 555]^2$$

... sperimentali CIE

P, D, T, V, V'

$$\log P = [c \cdot \lambda - c \cdot 570]^2$$

$$\log D = [c \cdot \lambda - c \cdot 540]^2$$

$$\log T = [c \cdot \lambda - c \cdot 450]^2$$

modello λ

