




OE580-7, Picture B1-030-0: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (sf); PS operators *settransfer*, 3 *colorimage*




OE580-5, Picture D2W-030-0: Radial gratings W-R_d; W-G_d; W-B_d; W-N; PS operator $\rightarrow \text{rgb}_d \text{ setrgbcolor}$




OE580-7, Picture D3W-030-0: 14 CIE-test colours and 2 + 16 grey steps; PS operator $\rightarrow \text{rgb}_d \text{ setrgbcolor}$


OE58: Test chart 4 according to ISO 15775, TR 24705; DH
Image, radial gratings, 16 step colour scales, Landolt-rings




OE581-1, Picture D4W-L-030-0: 16 equidistant steps W-R_d; W-G_d; W-B_d; W-N; PS: $\rightarrow \text{rgb}_d \text{ setrgbcolor}$



OE581-3, Picture D5W-030-0: Script and Landolt-rings N; R_d; G_d; B_d; Z; PS operator $\rightarrow \text{rgb}_d \text{ setrgbcolor}$



OE581-5, Picture D6W-L-030-0: Landolt-rings W-R_d; W-G_d; PS operator $\rightarrow \text{rgb}_d \text{ setrgbcolor}$



OE581-7, Picture D7W-L-030-0: Landolt-rings W-B_d; W-N; PS operator $\rightarrow \text{rgb}_d \text{ setrgbcolor}$

input: *rgb* ($\rightarrow \text{rgb}_d$) *setrgbcolor*
output 030-0: no change