



Farbmetrische Transformation $i = 0$
 $c_i^* = c_0^* = a c^{*b}$ mit $a = 1,00$; $b = 1,00$




LG710-1N, 1

Farbmetrische Transformation $i = 0$
 $c_i^* = c_0^* = a c^{*b}$ mit $a = 1,00$; $b = 1,00$




LG710-2N, 11

Farbmetrische Transformation $i = 4$
 $c_i^* = c_4^* = a c^{*b}$ mit $a = 0,75$; $b = 1,00$




LG711-1N, 5

Farbmetrische Transformation $i = 4$
 $c_i^* = c_4^* = a c^{*b}$ mit $a = 0,75$; $b = 1,00$




LG711-2N, 51

Farbmetrische Transformation $i = 1$
 $c_i^* = c_1^* = a c^{*b}$ mit $a = 1,00$; $b = 0,75$




LG710-3N, 2

Farbmetrische Transformation $i = 1$
 $c_i^* = c_1^* = a c^{*b}$ mit $a = 1,00$; $b = 0,75$




LG710-4N, 21

Farbmetrische Transformation $i = 5$
 $c_i^* = c_5^* = a c^{*b}$ mit $a = 0,50$; $b = 1,00$




LG711-3N, 6

Farbmetrische Transformation $i = 5$
 $c_i^* = c_5^* = a c^{*b}$ mit $a = 0,50$; $b = 1,00$




LG711-4N, 61

Farbmetrische Transformation $i = 2$
 $c_i^* = c_2^* = a c^{*b}$ mit $a = 1,00$; $b = 0,50$




LG710-5N, 3

Farbmetrische Transformation $i = 2$
 $c_i^* = c_2^* = a c^{*b}$ mit $a = 1,00$; $b = 0,50$




LG710-6N, 31

Farbmetrische Transformation $i = 6$
 $c_i^* = c_6^* = a c^{*b}$ mit $a = 0,25$; $b = 1,00$




LG711-5N, 7

Farbmetrische Transformation $i = 6$
 $c_i^* = c_6^* = a c^{*b}$ mit $a = 0,25$; $b = 1,00$




LG711-6N, 71

Farbmetrische Transformation $i = 3$
 $c_i^* = c_3^* = a c^{*b}$ mit $a = 1,00$; $b = 2,00$




LG710-7N, 4

Farbmetrische Transformation $i = 3$
 $c_i^* = c_3^* = a c^{*b}$ mit $a = 1,00$; $b = 2,00$




LG710-8N, 41

Farbmetrische Transformation $i = 7$
 $c_i^* = c_7^* = a c^{*b}$ mit $a = 0,00$; $b = 1,00$



LG711-7N, 8

Farbmetrische Transformation $i = 7$
 $c_i^* = c_7^* = a c^{*b}$ mit $a = 0,00$; $b = 1,00$



LG711-8N, 81