


http://130.149.60.45/~farbmetrik/PE46/PE46L0NP.PDF /.PS; start output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 1/2

see similar files: <http://130.149.60.45/~farbmetrik/PE46/PE46.HTM>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmetrik>



1-003031-L0

PE460-7N

Test chart G with 1080 colours; 9 or 16 step colour scales; data in column (A-n): **rgb** (A_j+k26_n27), 000n (k), w (l), nnn0 (m), www (n) + cmy0(all)



TUB-test chart PE46; standard test chart
1080 standard colours; image technology

input: *rgb/cmyk* -> *rgb/cmyk*
output: no change



see similar files: <http://130.149.60.45/~farbmetrik/PE46/PE46.HTM>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmetrik>

TUB registration: 20130201-PE46/PE46L0NP.PDF /.PS
application for measurement of offset print output, separation cmy0 (CMY0)
TUB material: code=rha4ta



1-003131-L0

PE460-70


TUB-test chart PE46; standard test chart
1080 standard colours, 3D=0, de=0, cmy0

input: *rgb/cmyk* -> *rgb_d*
output: transfer to *cmy0_d*

1-003131-F0






<http://130.149.60.45/~farbmetrik/PE46/PE46L0NP.PDF> /.PS; start output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 1/2



see similar files: <http://130.149.60.45/~farbmetrik/PE46/PE46.HTM>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmetrik>

TUB registration: 20130201-PE46/PE46L0NP.PDF /.PS
application for measurement of offset print output

TUB material: code=rha4ta




1-013031-L0

PE460-7N

Test chart G with 1080 colours; 9 or 16 step colour scales; data in column (A-n): **rgb** (A_j+k26_n27), 000n (k), w (l), nnn0 (m), www (n) + cmy0(all)

TUB-test chart PE46; standard test chart
1080 standard colours; image technology

input: *rgb/cmyk* -> *rgb/cmyk*
output: no change





http://130.149.60.45/~farbmetrik/PE46/PE46L0NP.PDF /.PS; transfer output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2



see similar files: <http://130.149.60.45/~farbmetrik/PE46/PE46.HTM>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmetrik>

TUB registration: 20130201-PE46/PE46L0NP.PDF /.PS
application for measurement of offset print output, separation cmy0 (CMY0)
TUB material: code=rha4ta



1-013131-L0

PE460-71

TUB-test chart PE46; standard test chart
1080 standard colours, 3D=0, de=1, cmy0

input: $rgb/cmyk \rightarrow rgb_e$
output: transfer to $cmy0_e$

1-013131-F0

