


N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2

see similar files: <http://130.149.60.45/~farbmeterik/PE60/PE60.HTM>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmeterik>



PE600-70

TUB-test chart PE60; hue plane yellow – blu
13 standard colours for D65, 3D=0, de=0

input: $rgb/cmyk \rightarrow rgb_d$
output: transfer to rgb_d