


<http://130.149.60.45/~farbmetrik/PE70/PE70L0NP.PDF> / .PS; start output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 1/2

Colour and Vision

Elementary Colours in Information Technology

see similar files: <http://130.149.60.45/~farbmetrik/PE70/PE70L0NP.PDF> / .PS; start output
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmetrik>



TUB registration: 20150701-PE70/PE70L0NP.PDF / .PS
application for measurement of display output

TUB material: code=rha4ta

<http://130.149.60.45/~farbmetrik>

1-003030-L0

PE700-7N

TUB-test chart PE70; hue circle; 16 and 8 steps
25 standard colours for D65

input: *rgb/cmyk* -> *rgb/cmyk*
output: no change