


http://130.149.60.45/~farbmatrik/RE96/RE96L0N1.TXT /PS; start output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 1/1

see similar files: <http://130.149.60.45/~farbmatrik/RE96/RE96L0N1.TXT>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmatrik>




RE96-3, Picture D1W--: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (sf); PS operator 3 colorimage



radial gratings W-R- radial gratings W-G- radial gratings W-B- radial gratings W-N radial gratings W-Z




RE96-5, Picture D2W--: radial gratings W-R-; W-G-; W-B-; W-N; PS operator rgb->rgb_ setrgbcolor




RE96-7, Picture D3W--: 14 CIE-test colours and 2 + 16 grey steps (sf); rgb/cmy0 set(rgb/cmyk)color


test chart RE96; 4(ISO/IEC 15775 + ISO/IEC TR 24705)
chromatic test chart RGB




RE96-1, Picture D4W--: 16 equidistant steps W-R-; W-G-; W-B-; W-N; rgb/cmy0 set(rgb/cmyk)color




RE96-1, Picture D5W--: Sipt and Landolt-rings N; R-; G-; B-; Z; PS operator rgb->rgb_ setrgbcolor



RE96-1, Picture D6W--: Landolt-rings W-R-; W-G-; PS operator rgb setrgbcolor



RE96-1, Picture D7W--: Landolt-rings W-B-; W-N; PS operator rgb setrgbcolor



RE96-1, Picture D8W--: Landolt-rings W-B-; W-N; PS operator rgb setrgbcolor



RE96-1, Picture D9W--: Landolt-rings W-B-; W-N; PS operator rgb setrgbcolor

TUB registration: 20130201-RE96/RE96L0N1.TXT /PS
application for measurement of display output

TUB material: code=rha4a