


T^* Amount of
threshold steps

• $L_g = 0,6 \text{ cd/m}^2$


x y
 A 0,39 0,41 LI 0,4s A
equation



T^* Amount of
threshold steps

• $L_g = 6 \text{ cd/m}^2$


x y
A 0,39 0,41 LI 0,4s A
equation



T^* Amount of
threshold steps

• $L_g = 60 \text{ cd/m}^2$


x y
A 0,39 0,41 LI 0,4s A
equation



T^* Amount of
threshold steps

• $L_g = 600 \text{ cd/m}^2$

x y
 A 0,39 0,41 LI 0,4s A
equation



T^* Amount of
threshold steps

• $L_g = 6000 \text{ cd/m}^2$

